

EXHIBIT B

ALTO LITIGATION, PC
Ellen London (Bar No. 325580)
ellen@altolit.com
Bess Ibtisam Hanish (Bar No. 325938)
bess@altolit.com
4 Embarcadero Center, Suite 1400
San Francisco, CA 94111
Telephone: (415) 779-2586
Facsimile: (415) 306-8744

THE STOUT FIRM, P.C.
Thomas D. Stout (Bar No. 241348)
tstout@stoutfirm.com
317 Washington Street, Suite 170
Oakland, CA 94607
Telephone: (415) 862-8485
Facsimile: (415) 862-8487

Attorneys for Interested Party
CN UTILITY CONSULTING, INC.

UNITED STATES DISTRICT COURT
FOR THE NORTHERN DISTRICT OF CALIFORNIA
SAN FRANCISCO DIVISION

UNITED STATES OF AMERICA,

Plaintiff,

v.

PACIFIC GAS AND ELECTRIC
COMPANY,

Defendant.

No. CR 14-00175-WHA

DECLARATION OF [REDACTED]
IN RESPONSE TO THE
COURT'S FEBRUARY 5, 2021 ORDER

I, [REDACTED], declare as follows:

1. I am currently employed by CN Utility Consulting ("CNUC" or the "Company").
2. My position at CNUC is Consulting Utility Forester ("CUF") III. As described in further detail below, I started at CNUC as a CUF I, and was promoted to the position of CUF III in October of 2019.
3. I have reviewed the Court's order in this matter, dated February 5, 2021, Docket No. 1297.

1 4. I have reviewed the photograph at Docket No. 1250-4 and page 11 of the Court's
2 order dated December 29, 2020, in which the Court specifically identifies a gray pine (the "Gray
3 Pine") shown at Docket No. 1250-4.

4 5. Based on having reviewed the photograph and the description described in the
5 order, I believe I understand which tree the Court is referring to when it discusses the "Gray Pine"
6 in the February 5, 2021 Order.

7 6. I submit this declaration in response to the Court's February 5, 2021 Order.

8 **I. QUALIFICATIONS AND LICENSE**

9 7. I was hired by CNUC as a CUF 1 on April 10, 2017.

10 8. When I started at CNUC, I was given a binder of training materials, which I
11 reviewed, and I was given on-the-job training in which I spent a several weeks with a Senior
12 Consulting Utility Forester ("SCUF"). I was also trained on the job by several other CUFs,
13 including [REDACTED]; I spent time learning from these CUFs in the field.

14 9. I was trained on the basics of vegetation management ("VM"), and at CNUC we
15 were given regular training updates on VM issues (in addition to various trainings on other
16 issues), prior to the pandemic. I understand the rules regarding distance from the power lines and
17 other issues that might affect power lines. I also understand the rules for how to respond to trees
18 that are hazardous.

19 10. In particular, I am familiar with the requirements of General Order 95 and Rule 35,
20 as well as the Public Resource Code Section 4293 Power Line Fire Prevention Field Guide. I
21 received both initial and recurring training on these standards throughout my time at CNUC.

22 11. In general, I am familiar with the rules of compliance for my job as a forester.

23 12. I am now in a position in which I am training new CUFs.

24 13. I do not have a license or other formal certification.

25 14. I have studied for the International Society of Arboriculture ("ISA") certification
26 exam, and I was planning to take it as soon as I became eligible (which was April 2020); however,
27 testing was delayed due to the COVID-19 pandemic. While testing has resumed, I have not yet
28 taken it.

1 15. When I conduct a routine patrol, I walk both sides of the length of the power line
2 for the area I am inspecting from one pole to the next. I am looking for (1) any tree that, due to
3 proximity to the power lines, must be trimmed or removed to be brought into compliance with
4 VM standards, and (2) trees that are at high risk of falling on the power line regardless of whether
5 they are encroaching on power lines, for example dead or dying trees or trees that show signs of
6 root decay or ground disturbance. I focus on growth and strength.

7 16. It is not within the scope of a routine patrol to mark a green and healthy tree for
8 trimming or removal that is otherwise in compliance with VM standards.

9 17. When in doubt, my practice is to err on the side of caution in marking more trees
10 for trimming or removal.

11 **II. DATE OF GRAY PINE DETERMINATION**

12 18. I was responsible for the routine patrol of Route 50 of the Girvan 1101 Circuit,
13 including Zogg Mine Road, in 2019 and in 2020. I was also responsible for this patrol in 2017.

14 19. [REDACTED], another CNUC CUF and colleague of mine, accompanied me on
15 these patrols. [REDACTED] came with me because there were approximately twenty spans located in
16 extremely challenging terrain that he was better able to access, most of which were not on Zogg
17 Mine Road. He was only with me for two to three days out of the total of approximately three
18 weeks it took me to complete the whole patrol. Having reviewed the photograph at Docket No.
19 1250-4, I am familiar with that area, do not regard the terrain as unusually challenging, and
20 believe I would have inspected that segment of Route 50 personally.

21 20. I have also reviewed reports I caused to be generated through PG&E's Getac
22 Preload during the course of the 2019 and 2020 routine inspections of Route 50. I generated all
23 reports created during both inspections; none were created by [REDACTED].

24 21. I do not recall the Gray Pine from my patrols, although it was within the area of my
25 patrols. Based on my review of VMD data, I would have inspected the area in the vicinity of the
26 Gray Pine during the 2019 routine patrol on April 15, 2019; April 24, 2019; and April 26, 2019.
27 Copies of these records are attached hereto as Exhibits 1, 2, and 3, respectively. Based on my
28 review of VMD data, I would have inspected the area in the vicinity of the Gray Pine during the

2020 routine patrol on March 23, 2020, and March 26, 2020. Copies of these records are attached at Exhibits 4 and 5, respectively.

22. While I do not recall this specific tree, as noted above, I have seen a photograph of it. *See* Docket No. 1250-4. Looking at this photograph, I do not believe I would have had a bad feeling about this tree. In my view, it is green, and the lean is not severe for a gray pine. The tree appears to have a black base from being burned, which is a common situation and not a sign of an unhealthy tree.

III. INVESTIGATION OF GRAY PINE

23. As discussed above, I do not recall the Gray Pine from my patrols.

24. As also discussed above, I would have walked along the power line in the area in which the Gray Pine is located.

25. I do not know for sure but would guess that I probably was within roughly 50 feet of the Gray Pine while walking the line. I do not believe that I would have inspected all sides of it, because, as explained above, there was nothing about this tree that would have led me to think it needed a closer inspection beyond being able to see it while walking the line.

26. In February 2019, the Redding area, including Route 50 of the Girvan 1101 Circuit, experienced abnormally heavy snow fall. As a result, during my routine patrol in April 2019, I saw an unusually large number of trees that had suffered damage and needed to be marked for trimming or removal. Any tree that, after that extreme snow fall event, appeared healthy and undamaged is a tree that I would have regarded as robustly strong and healthy because most weaker trees showed obvious signs of damage.

27. Although I do not specifically remember the Gray Pine, based on my review of the photograph at Docket No. 1250-4, which I understand to have been taken in July 2019, I would have regarded the Gray Pine as a particularly healthy tree due to having survived the February 2019 extreme snow fall event without any obvious signs of damage

IV. PHOTOGRAPHS, NOTES, OR VIDEOS

28. As discussed above, I do not recall the Gray Pine from my patrols.

29. My general practice with regard to photographs and notes is to only write down notes reflecting customers' contact information, or, on occasion, notes to remind myself of something. Everything else is reflected in the official report.

30. I do not take videos while I am patrolling.

31. I have confirmed that I do not have any photographs, notes, or videos from the routine patrols of this area.

V. REPORTS

32. As discussed above, I do not recall the Gray Pine from my patrols.

33. I have attached the reports that I generated from the routine patrols discussed above in the areas in the vicinity of the Gray Pine as Exhibits 1, 2, 3, 4, and 5. There is no mention of the Gray Pine in the reports because I did not mark it for trimming or removal. It was not my practice to generate reports or take notes of healthy trees that were otherwise in compliance with VM standards.

VI. REASONS RE: NOT MARKING GRAY PINE

34. As discussed above, I do not recall the Gray Pine from my patrols. However, in looking at a photograph of it, I do not see any reason that I would have marked it for removal. It appears to be a healthy-looking gray pine that was in compliance with VM standards that would not qualify for removal.

VII. KNOWLEDGE RE: GRAY PINE

35. As discussed above, I do not recall the Gray Pine from my patrols. However, I have looked at a photograph of the tree, and I can see that if the tree were to fall, it would fall in the direction of the power line.

36. As also discussed above, I do not regard the degree of lean of the Gray Pine as extreme. There are countless healthy trees along Route 50 of the Girvan 1101 Circuit that are large enough to fall on a power line and lean toward the line, but are healthy and in compliance with applicable VM standards. In my experience, preliminary inspectors do not mark such trees for trimming or removal.

1 37. Having reviewed the photograph at Docket No. 1250-4, I do not believe I would
2 have regarded the Gray Pine as presenting a heightened danger to the power line based solely on
3 the degree of lean.

4 I declare under penalty of perjury under the laws of the United States that the foregoing is
5 true and correct.

6
7 DATED: February 11, 2021




EXHIBIT 1

Cust.Inf. | **MAP** | **History**

Inspection Record Detail

City: IGO		County: SH		Directions: S/ON PLACER>W/ON SOUTH FORK RD>N/ON ZOGG MINE; N/OFF LARRY HORSE LN				Inspector / Company: - CNU					
Division: North Valley	Circuit: (0103401101) GIRVAN 1101	SSD #: 4855	SSD Rte #: 50	Routing #: 1365	Area: P-25	SRA: Yes	Alerts: AX LG NF						
Insp Date / Time: 4/15/2019 4:46:52 PM	Tag Type:	Tag Number:	Line Name:		Pole Num:	Quad Map: C-6	Removal #: 3872272	Customer Name/Phone:					
Comment: P58 TP ON DRWY @ 1ST DRWY ENT PAST 8455 ADD FLGD GT P59 IS/W/OF P58 TP ABOVE ZOGG MINE RD CUST WANTS TO KNOW WHO IS ON PROPERTY.MUST CALL TO HAVE GT OPENED.													
							Audit	Last Edit: 4/15/2019 4:46:52 PM by: [REDACTED]					
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
1	Live Oak	CA	Routine	No	Private	23 7	16 Inside	Rtn	1	TopDirecti	M		4/15/2019 4:46:52 PM
	Comment: .1S/E/OF P59				Notification:	Work Request: SHNV1024545		WC Date: 12/20/2017	WC Qty: 1	WC Trim: TD	Completed By: [REDACTED]	Invoice: TR (104)	
	Lat/Long: 40.538658, -122.562043 Google Map!				External TreeID: W122562043N40538658						Audit	Last Edit: 4/15/2019 4:52:34 PM by: [REDACTED]	
	Rx Comment:												
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
2	Gray Pine	CA	Routine	No	Private	80 22	99 Inside	Rtn	1	FP-Rmv2 B	M		4/15/2019 4:48:46 PM
	Comment: .2S/E/OF P59				Notification: OK	Work Request: C1NV1001887		WC Date: 5/31/2019	WC Qty: 1	WC Trim: F2B	Completed By: [REDACTED]	Invoice: B2 (104)	
	Lat/Long: 40.544415, -122.575775 Google Map!				External TreeID: W122575775N40544415						Audit	Last Edit: 4/15/2019 4:48:46 PM by: [REDACTED]	
	Rx Comment:												
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
3	Live Oak	CA	Routine	No	Private	35 12	13 Inside	Rtn	1	Side	M		6/20/2016 3:51 PM
	Comment: .2S/E/OF P59				Notification:	Work Request: SHNV1022869		WC Date: 11/21/2016	WC Qty: 1	WC Trim: SD	Completed By: [REDACTED]	Invoice: TR (104)	
	Lat/Long:				External TreeID:				ANNUAL TRIM		Audit	Last Edit: 4/15/2019 4:52:34 PM by: [REDACTED]	
	Rx Comment:												
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
4	Black Oak	CA	Routine	No	Private	35 12	99 Inside	Rtn	1	FP-Rmv2 B	M		4/15/2019 4:46:51 PM
	Comment: .2S/E/OF P59;DEAD				Notification: OK	Work Request: C1NV1001887		WC Date: 5/31/2019	WC Qty: 1	WC Trim: F2B	Completed By: [REDACTED]	Invoice: B2 (104)	
	Lat/Long: 40.544472, -122.575661 Google Map!				External TreeID: W122575661N40544472						Audit	Last Edit: 4/15/2019 4:46:51 PM by: [REDACTED]	
	Rx Comment:												
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
5	Gray Pine	CA	Routine	No	Private	80 14	99 Inside	Rtn	1	FP-Rmv2 B	M		4/15/2019 4:52:25 PM
	Comment: .2S/E/OF P59				Notification: OK	Work Request: C1NV1001887		WC Date: 5/31/2019	WC Qty: 1	WC Trim: F2B	Completed By: [REDACTED]	Invoice: B2 (104)	
	Lat/Long: 40.539343, -122.565038 Google Map!				External TreeID: W122565038N40539343						Audit	Last Edit: 4/15/2019 4:52:25 PM by: [REDACTED]	
	Rx Comment:												

EXHIBIT 2

Cust.Inf. | MAP | History

Inspection Record Detail

A				City:	County:	Directions:				Inspector / Company:					
				IGO	SH	S/ON PLACER>W/ON SOUTH FORK RD>N/ON ZOGG MINE; N/OF LARRY HORSE LN				- CNU					
Division:	Circuit:	SSD #:	SSD Rte #:	Routing #:	Area:		SRA	Alerts:							
North Valley	GIRVAN 1101	4855	50	1390	P-25		Yes	AX LG NF PI							
Insp Date / Time:	Tag Type:	Tag Number:	Line Name:			Pole Num:	Quad Map:	Removal #:	Customer Name / Phone:						
4/24/2019 12:49:26 PM							C-6	3872272							
Comment: P58 TP ON DRWY 1ST DRWY ENT PAST PSTD ADD 8455 FLGD GT P61 3S/W/OF P58 TP ABOVE ZOGG MINE RD CAN AX FROM RD UP HILL CUST WANTS TO KNOW WHO IS ON PROPERTY.															
Audit Last Edit: 4/24/2019 12:49:26 PM by:															
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height	DBH	Clearance	Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
1	Live Oak	CA	Routine	No	Private	55	32	99	Inside	Rtn	1	FS-R3B+Trt	M		10/12/2018 9:34:42 AM
Comment: 1S/W/OF P61; 2 XSTEM, DEAD						Notification:		Work Request: C1NV1001518		WC Date: 2/15/2019	WC Qty: 1	WC Trim: F2D	Completed By:	Invoice: D2 (104)	
Lat/Long: 40.539322, -122.56367 Google Map!						External TreeID: W122563670N40539322						Audit		Last Edit: 4/24/2019 12:53:51 PM by:	
Rx Comment: TREE WAS WORKED FOR FIRE BUT STILL POSSES A THREAT T LINES															
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height	DBH	Clearance	Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
2	Knobcone Pine	CA	No Trim	No	Private	20	4		Inside	Rtn		TopDirecti	M		6/25/2012 1:11:11 PM
Comment: 1S/W/O P61						Notification:		Work Request:		WC Date:	WC Qty:	WC Trim:	Completed By:	Invoice: Not Worked	
Lat/Long:						External TreeID:						Audit		Last Edit: 4/24/2019 12:53:51 PM by:	
Rx Comment:															
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height	DBH	Clearance	Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
3	Ponderosa Pine	CA	Routine	No	Private	100	31	99	Inside	Rtn	2	FP-Rmv3 B	M		4/24/2019 1:11:11 PM
Comment: 4-5S/W/OF P61; AVG DBH AND HT						Notification: OK		Work Request: SHNV1026375		WC Date: 5/8/2019	WC Qty: 2	WC Trim: F3B	Completed By:	Invoice: B3 (104)	
Lat/Long: 40.539495, -122.56493 Google Map!						External TreeID: W122564930N40539495						Audit		Last Edit: 4/24/2019 12:51:12 PM by:	
Rx Comment:															
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height	DBH	Clearance	Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
4	Gray Pine	CA	No Trim	No	Private	70	16	20	Inside	Rtn	2	Side	M		6/25/2012 1:11:11 PM
Comment: 1S/W/O P61						Notification:		Work Request:		WC Date:	WC Qty:	WC Trim:	Completed By:	Invoice: Not Worked	
Lat/Long:						External TreeID:						Audit		Last Edit: 4/24/2019 12:53:51 PM by:	
Rx Comment:															

EXHIBIT 3

Cust.Inf. | **MAP** | **History**

Inspection Record Detail

Division: North Valley				Circuit: (0103401101) GIRVAN 1101		SSD #: 4855		SSD Rte #: 50		Routing #: 1370		City: IGO		County: SH		Directions: S/ON PLACER>W/ON SOUTH FORK RD>N/ON ZOGG MINE; N/O LARRY HORSE LN				Inspector / Company: [REDACTED] - CNU	
Insp Date / Time: (preload) 4/15/2019 4:55:09 PM				Tag Type:		Tag Number:		Line Name:				Pole Num:		Quad Map: C-6		Removal #: 3872272		Alerts: AX NF PI			
Comment: P58 TP ON DRWY @ 1ST DRWY ENT PAST 8455 ADD FLGD GT P59 IS/W/OF P58 TP ABOVE ZOGG MINE RD CUST WANTS TO KNOW WHO IS ON PROPERTY.MUST CALL TO HAVE GT OPENED.																					
																		Audit		Last Edit: 4/15/2019 4:55:09 PM by: [REDACTED]	
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height	DBH	Clearance	Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:						
1	Live Oak	CA	Routine	No	Private	45	9	Inside		Rtn	1	FS-R1A+Trt	M			10/12/2018	9:15:53 AM				
Comment: @ P59; DEAD+ROT, UP HILL						Notification:		Work Request: C1NV1001518		WC Date: 2/15/2019		WC Qty: 1		WC Trim: F1D		Completed By: [REDACTED]		Invoice: XX (104)			
Lat/Long: 40.538677, -122.562037 Google Map!						External TreeID: W122562037N40538677						Audit		Last Edit: 4/15/2019 4:57:45 PM by: [REDACTED]							
Rx Comment:																					
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height	DBH	Clearance	Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:						
2	Gray Pine	CA	Routine	No	Private	45	8	99	Inside	Rtn	1	FP-Rmv1 A	M			10/12/2018	9:15:53 AM				
Comment: @ P59; DEAD, UP HILL						Notification:		Work Request: C1NV1001518		WC Date: 2/15/2019		WC Qty: 1		WC Trim: F1B		Completed By: [REDACTED]		Invoice: XX (104)			
Lat/Long: 40.53868, -122.562035 Google Map!						External TreeID: W122562035N40538680						Audit		Last Edit: 4/15/2019 4:57:45 PM by: [REDACTED]							
Rx Comment:																					
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height	DBH	Clearance	Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:						
3	Gray Pine	CA	Routine	No	Private	35	9	99	Inside	Rtn	1	Rmv 1-A	M			4/15/2019	4:57:53 PM				
Comment: .3S/W/OF P59;						Notification: OK		Work Request: SHNV1026375		WC Date: 5/24/2019		WC Qty: 1		WC Trim: R1A		Completed By: [REDACTED]		Invoice: R1 (104)			
Lat/Long: 40.521655, -122.552467 Google Map!						External TreeID: W122552467N40521655						Audit		Last Edit: 4/26/2019 1:37:59 PM by: [REDACTED]							
Rx Comment: TREE HAS DOT, NO X																					
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height	DBH	Clearance	Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:						
4	Live Oak	CA	Routine	No	Private	25	33	16	Inside	Rtn	1	Slope	M			4/15/2019	4:57:53 PM				
Comment: .4S/W/OF P59;XSTM						Notification: OK		Work Request: SHNV1026375		WC Date: 5/24/2019		WC Qty: 1		WC Trim: SL		Completed By: [REDACTED]		Invoice: TR (104)			
Lat/Long: 40.538212, -122.561195 Google Map!						External TreeID: W122561195N40538212						Audit		Last Edit: 4/15/2019 4:55:51 PM by: [REDACTED]							
Rx Comment:																					
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height	DBH	Clearance	Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:						
5	Gray Pine	CA	Routine	No	Private	85	24	15	Inside	Rtn	1	FP-Ov A	M			10/12/2018	5 AM				
Comment: .3S/W/OF P59; REMOVE DEAD LIMB						Notification:		Work Request: C1NV1001518		WC Date: 2/15/2019		WC Qty: 1		WC Trim: FOA		Completed By: [REDACTED]		Invoice: XX (104)			
Lat/Long: 40.538678, -122.56236 Google Map!						External TreeID: W122562360N40538678						Audit		Last Edit: 4/15/2019 4:57:45 PM by: [REDACTED]							
Rx Comment:																					
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height	DBH	Clearance	Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:						
6	Gray Pine		No Trim	No	Private	80	23		Inside	Rtn	1	Side	M			6/25/2012	1:47:14 PM				
Comment: .3 & .4S/W/O P59						Notification:		Work Request:		WC Date:		WC Qty:		WC Trim:		Completed By:		Invoice: Not Worked			

Tree Number 7	Lat/Long:					External TreeID:					<u>Audit</u>		Last Edit: 4/15/2019 4:57:45 PM by: [REDACTED]		
	Rx Comment:														
	Tree Species: Live Oak	Crew: CA	Priority: Routine	TGR: No	Owned By: Private	Height 40	DBH 26	Clearance 14	Prox: Inside	Cycle: Rtn	Qty: 1	Trim Type: Top	Account: M	Wire Conditions:	Insp Date: 4/15/2019 4: [REDACTED] PM
	Comment: .9S/W/O P59;XSTM					Notification: OK		Work Request: SHNV1026375			WC Date: 5/31/2019	WC Qty: 1	WC Trim: TO	C [REDACTED]	Invoice: TR (104)
Lat/Long: 40.532147, -122.556123 Google Map!					External TreeID: W122556123N40532147							<u>Audit</u>		Last Edit: 4/15/2019 4:56:15 PM by: [REDACTED]	
Rx Comment:															

EXHIBIT 4

Cust.Inf. | MAP | History

Inspection Record Detail

A				City:	County:	Directions:				Inspector / Company:			
[REDACTED]				IGO	SH	S/ON PLACER>W/ON SOUTH FORK RD>N/ON ZOGG MINE; N/OF LARRY HORSE LN				[REDACTED] - CNU			
Division:	Circuit: (0103401101)	SSD #:	SSD Rte #:	Routing #:			Area:	SRA	Alerts:				
North Valley	GIRVAN 1101	4855	50	1350			P-25	Yes	LG NF PI				
Insp Date / Time: (preload)	Tag Type:	Tag Number:	Line Name:			Pole Num:	Quad Map:	Removal #:	Phone:				
3/23/2020 3:07:19 PM							C-6	4051296	[REDACTED]				
Comment: P58 TP ON DRWY. 1ST DRWY PAST PSTD ADD 8455 FLGD GT EP 1S/N/OF P58 TP CUST WANTS TO KNOW WHO IS ON PROPERTY.MUST CALL TO GET KEY [REDACTED]. LOW SPAN.													
										Audit		Last Edit: 3/23/2020 3:07:19 PM by: [REDACTED]	
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
1	Oak	CA	Routine	No	Private	40 25	13 Inside	Rtn	1	TopDirecti	M		8/18/2014 2:54:39 PM
Comment:						Notification:		Work Request:		WC Date:	WC Qty:	WC Trim:	Completed By:
.1S/N/O P58 TP; SD/TOO 12', TRIM BTH LINE'S								SHNV1020839		10/15/2014	1	TD	[REDACTED] Invoice: TR (104)
Lat/Long:						External TreeID:						Audit	
Rx Comment:													
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
2	Other	CA	Routine	No	Private	25 12	12 Inside	Rtn	1	TopDirecti	M		6/14/2012 1:00:00 PM
Comment:						Notification:		Work Request:		WC Date:	WC Qty:	WC Trim:	Completed By:
MANZI .2S/N/O P58 TP. XSTM								SHNV1018602		8/7/2012	1	TD	[REDACTED] Invoice: TR (104)
Lat/Long:						External TreeID:						Audit	
Rx Comment:													
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
3	Live Oak	CA	Routine	No	Private	40 30	12 Inside	Rtn	1	TopDirecti	M		6/30/2015 9:00:00 AM
Comment:						Notification:		Work Request:		WC Date:	WC Qty:	WC Trim:	Completed By:
.2S/N/O P58 TP. XSTM								SHNV1021775		9/16/2015	1	TD	[REDACTED] Invoice: TR (104)
Lat/Long:						External TreeID:						Audit	
40.538271667, -122.560863333 Google Map!												Last Edit: 3/23/2020 3:21:21 PM by: [REDACTED]	
Rx Comment:													
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
4	Interior Live Oak	CA	Routine	No	Private	30 38	14 Inside	Rtn	1	Top	M		3/23/2020 3:09:56 PM
Comment:						Notification:		Work Request:		WC Date:	WC Qty:	WC Trim:	Completed By:
.3S/N/OF P58 TP. SNOW BENT						OK		SHNV1029070		4/13/2020	1	FAB	[REDACTED] Invoice: BA (104)
Lat/Long:						External TreeID:						Audit	
40.538267, -122.5608 Google Map!						W122560800N40538267						Last Edit: 3/23/2020 3:09:56 PM by: [REDACTED]	
Rx Comment:						TOP ALL LINE SIDE LEADS TO BELOW LINES. TAKE BIG WOOD; NEW CONSTRUCTION							
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
5	Gray Pine	CA	Routine	No	Private	18 2	99 Inside	Rtn	1	Br Rmv	M		10/12/2018 8:52:55 AM
Comment:						Notification:		Work Request:		WC Date:	WC Qty:	WC Trim:	Completed By:
.4S/N/OF P58 TP; UNDERLINE								SHNV1025651		10/31/2018	1	BC	[REDACTED] Invoice: XX (104)
Lat/Long:						External TreeID:						Audit	
40.538335, -122.56081 Google Map!						W122560810N40538335						Last Edit: 3/23/2020 3:21:21 PM by: [REDACTED]	
Rx Comment:													
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
6	Blue Oak	CA	Routine	No	Private	40 12	12 Inside	Rtn	1	Side	M		6/30/2015 9:10:12 AM
Comment:						Notification:		Work Request:		WC Date:	WC Qty:	WC Trim:	Completed By:
.5S/N/O P58 TP; XSTEM ,E/SD								SHNV1021775		9/16/2015	1	SD	[REDACTED] Invoice: TR (104)
Lat/Long:						External TreeID:						Audit	
40.538505, -122.56084 Google Map!												Last Edit: 3/23/2020 3:21:21 PM by: [REDACTED]	

EXHIBIT 5

Cust.Inf. | MAP | History

Inspection Record Detail

A				City:	County:	Directions:				Inspector / Company:			
[REDACTED]				IGO	SH	S/ON PLACER>W/ON SOUTH FORK RD>N/ON ZOGG MINE; N/O LARRY HORSE LN				[REDACTED] - CNU			
Division:	Circuit: (0103401101)	SSD #:	SSD Rte #:	Routing #:	Area:		SRA	Alerts:					
North Valley	GIRVAN 1101	4855	50	1370	P-25		Yes	AX NF PI					
Insp Date / Time: (preload)	Tag Type:	Tag Number:	Line Name:			Pole Num:	Quad Map:	Removal #:	Customer Name/Phone:				
3/26/2020 2:37:15 PM							C-6	4051296	[REDACTED]				
Comment: P58 TP ON DRWY @ 1ST DRWY ENT PAST 8455 ADD FLGD GT P59 IS/W/OF P58 TP ABOVE ZOGG MINE RD CUST WANTS TO KNOW WHO IS ON PROPERTY.MUST CALL TO HAVE GT OPENED.													
										Audit		Last Edit: 3/26/2020 2:37:15 PM by: [REDACTED]	
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date: (J924)
1	Canyon Live Oak	CA	Routine	No	Private	40 16	99 Inside	Rtn	1	FS-R2B+Trt	M		3/26/2020 2:37:15 PM
	Comment:					Notification:		Work Request:		WC Date:	WC Qty:	WC Trim:	Invoice:
	.3S/W/OF P59; DEAD					OK		C1NV1002839		4/14/2020	1	F3B	B3 (104)
	Lat/Long:					External TreeID:					Audit		Last Edit:
40.538677, -122.562037 Google Map!					W122562037N40538677							4/1/2020 9:46:08 AM by: [REDACTED]	
Rx Comment:													
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
2	Gray Pine	CA	Routine	No	Private	45 8	99 Inside	Rtn	1	FP-Rmv1 A	M		10/12/2018 9:15:55 AM
	Comment:					Notification:		Work Request:		WC Date:	WC Qty:	WC Trim:	Invoice:
	@ P59; DEAD, UP HILL							C1NV1001518		2/15/2019	1	F1B	XX (104)
	Lat/Long:					External TreeID:					Audit		Last Edit:
40.53868, -122.562035 Google Map!					W122562035N40538680							3/26/2020 2:39:34 PM by: [REDACTED]	
Rx Comment:													
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
3	Gray Pine	CA	Routine	No	Private	35 9	99 Inside	Rtn	1	Rmv 1-A	M		4/15/2019 4:00 PM
	Comment:					Notification:		Work Request:		WC Date:	WC Qty:	WC Trim:	Invoice:
	.3S/W/OF P59;							SHNV1026375		5/24/2019	1	R1A	R1 (104)
	Lat/Long:					External TreeID:					Audit		Last Edit:
40.521655, -122.552467 Google Map!					W122552467N40521655							3/26/2020 2:39:34 PM by: [REDACTED]	
Rx Comment:													
TREE HAS DOT, NO X													
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
4	Gray Pine	CA	Routine	No	Private	85 24	15 Inside	Rtn	1	FP-Ov A	M		10/12/2018 5:00 AM
	Comment:					Notification:		Work Request:		WC Date:	WC Qty:	WC Trim:	Invoice:
	.3S/W/OF P59; REMOVE DEAD LIMB							C1NV1001518		2/15/2019	1	FOA	XX (104)
	Lat/Long:					External TreeID:					Audit		Last Edit:
40.538678, -122.56236 Google Map!					W122562360N40538678							3/26/2020 2:39:34 PM by: [REDACTED]	
Rx Comment:													
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
5	Canyon Live Oak	CA	Routine	No	Private	34 32	14 Inside	Rtn	1	FP-Trim B	M		3/26/2020 2:00 PM
	Comment:					Notification:		Work Request:		WC Date:	WC Qty:	WC Trim:	Invoice:
	.7S/W/OF P59;XSTM					OK		C1NV1002839		4/14/2020	1	FAB	BA (104)
	Lat/Long:					External TreeID:					Audit		Last Edit:
40.532147, -122.556123 Google Map!					W122556123N40532147							4/1/2020 9:45:47 AM by: [REDACTED]	
Rx Comment:													
Tree Number	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height DBH	Clearance Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:
6	Gray Pine	CA	Routine	No	Private	40 24	99 Inside	Rtn	1	FS-R3B+Trt	M		3/26/2020 2:00 PM
	Comment:					Notification:		Work Request:		WC Date:	WC Qty:	WC Trim:	Invoice:
	.9S/W/OF P59; S/SD/LNS					OK		C1NV1002839		4/14/2020	1	F3D	D3 (104)
	Lat/Long:					External TreeID:					Audit		Last Edit:

	40.539843, -122.566332 Google Map!		W122566332N40539843				Audit		3/26/2020 2:41:50 PM by: [REDACTED]							
Rx Comment:																
Tree Number 7	Tree Species:	Crew:	Priority:	TGR:	Owned By:	Height	DBH	Clearance	Prox:	Cycle:	Qty:	Trim Type:	Account:	Wire Conditions:	Insp Date:	
	Canyon Live Oak	CA	Routine	No	Private	33	15	99	Inside	Rtn	1	FS-R2B+Trt	M		3/26/2020 2:43:20 PM	
	Comment: .9S/W/OF P59;					Notification: OK		Work Request: C1NV1002839		WC Date: 4/14/2020		WC Qty: 1		WC Trim: F2D	C [REDACTED] y: [REDACTED]	Invoice: D2 (104)
	Lat/Long: 40.538212, -122.561195 Google Map!					External TreeID: W122561195N40538212							Audit		Last Edit: 3/26/2020 2:43:20 PM by: [REDACTED]	
Rx Comment:																